## Server Automation Alert: Heartbleed OpenSSL Bug Vulnerability

(April 28, 2014)

**ACTION**: Deploy the SA Software Repository Download Accelerator (Tsunami) - NGINX Update SRVA 00174

The information in this alert should be acted upon right away.



Issue that Requires Attention	2
Impact on SA	2
Immediate Mitigation	2
Performing Pre-Update Steps	3
Re-Enabling the Accelerator on SA 10.00 Cores	3
Re-Enabling the Accelerator on SA 10.01 Cores and Satellites	3
Applying the SA Software Repository Download Accelerator (Tsunami) - NGINX Update	3
Applying the Fix	3
Verifying the Fix	4
Stolen Private Key	4

#### **Change Table for this Document**

Date	Change
April 14, 2014	Initial Release
April 28, 2014	The SA Software Repository Download Accelerator (Tsunami) – NGINX Update fix is introduced. This fix modifies the SA Software Repository Download Accelerator component (also known as the Accelerator, or tsunami in this document) so that it is no longer vulnerable to the Heartbleed bug.  After you run this update, the Accelerator becomes re-enabled, to benefit from the improved download performance it provides.

## **Issue that Requires Attention**

The Heartbleed bug (CVE-2014-0160) is a vulnerability found in the OpenSSL cryptographic software library.

This vulnerability allows an attacker to:

- Steal the information typically protected by the SSL/TLS protocol.
- Read the memory of the systems using vulnerable versions of OpenSSL.
- Steal the SSL private key (used for SSL encryption) and therefore compromise all data encrypted by the key. Stealing the key allows attackers to eavesdrop on communications, steal data directly from the server, and impersonate services and end users.

You cannot verify, with 100% certainty, that your environment has not already been compromised.

#### **Vulnerability Origin:**

- 1 Direct use of affected OpenSSL version libraries
- 2 Web/Application servers using affected OpenSSL version libraries
- 3 Operating system that includes affected OpenSSL version libraries

Note: See also the following HPSW Security Bulletin:

https://h20564.www2.hp.com/portal/site/hpsc/public/kb/docDisplay/?docId=emr\_na-c04236102

## Impact on SA

The SA Software Repository Download Accelerator component running on the following versions of SA component hosts is vulnerable to the Heartbleed bug:

- SA 10.00 and 10.01 slice servers
- SA 10.01 satellite servers

No other supported versions of SA are affected.

**Note**: In this document, the SA Software Repository Download Accelerator is referred to as "the Accelerator" or "tsunami."

### **Immediate Mitigation**

To make sure that the Heartbleed bug will not affect your SA System, complete the steps in the following sections:

- Performing Pre-Update Steps
- Applying the SA Software Repository Download Accelerator (Tsunami) NGINX Update

Server Automation Alert Page 2

#### **Performing Pre-Update Steps**

In the previous version of this memo, you were advised to disable the Accelerator to secure your environment against the Heartbleed bug. Disabling the Accelerator caused Software Repository downloads to bypass the Accelerator and revert to the traditional Software Repository access methods, which might result in slower performance, depending on the demands of your environment.

Disabling the Accelerator is no longer necessary. If you previously disabled the Accelerator, you must reenable it to restore download performance in your SA environment.

**Note:** You only need to perform these pre-update steps if you already disabled the Accelerator, as the earlier version of this memo advised you to do.

#### Re-Enabling the Accelerator on SA 10.00 Cores

To re-enable the Accelerator on SA 10.00 Cores, issue the following commands:

```
# cd /etc/opt/opsware/startup
# mv tsunami.disabled tsunami
```

#### Re-Enabling the Accelerator on SA 10.01 Cores and Satellites

To re-enable the Accelerator on SA 10.01 Cores and Satellites, issue the following command:

# rm /var/opt/opsware/tsunami/tsunami.disabled

# Applying the SA Software Repository Download Accelerator (Tsunami) - NGINX Update

The SA Software Repository Download Accelerator (Tsunami) – NGINX Update (QCCR1D183160) is a fix for the affected binary that was compiled with the vulnerable version of OpenSSL (1.0.1c). The updated nginx binary is now compiled against OpenSSL 1.0.1g

To download and run the fix, go to:

http://support.openview.hp.com/selfsolve/document/LID/SRVA 00174

**Note:** For SA versions 10.00 and 10.01, you must apply the fix to each slice on the SA Core. In addition, for SA 10.01, you must also apply the fix on each satellite server in the mesh. Contact HP Support for additional assistance.

#### Applying the Fix

To apply the fix, issue the following commands:

```
[root@dc1 ~]# tar -xvzf QC183160_10.01.NGINX_49064.tar.gz
[root@dc1 ~]# cd QC183160_10.01.NGINX_49064
[root@dc1 QC183160_10.01.NGINX_49064]# ./patch.sh -v install
```

After you apply the fix, the Accelerator starts automatically.

Server Automation Alert Page 3

#### Verifying the Fix

To verify the fix, run the list open files (1sof) command and confirm that the results are as expected.

To run the 1sof command:

```
[root@dc1 ~]# lsof -i:8061
```

The expected output of the 1sof command (as the following example illustrates) will show that there are NGINX processes listening on port 8061:

	COMMAND	PID	USER	FD	TYPE	DEVICE	SIZE	NODE	NAME	
	nginx	7111	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7112	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7113	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7115	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7116	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7117	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7118	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7119	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
	nginx	7120	root	7u	IPv4	17594		TCP	*:8061	(LISTEN)
[root@dc1 ~]#										

Note: Contact HP Support for additional assistance if your results are not similar to the example output.

## **Stolen Private Key**

If an attacker has already obtained the Software Repository component's wordbot private key, your SA environment can potentially be compromised.

Depending on your SA expertise, your SA environment, and the probability that the private key was compromised, you might consider performing the following additional actions:

Reinstallation of your SA environment to regenerate the crypto material (Contact HP Support for additional assistance.)

SA core recertification

(Contact Support/CPE for assistance. Additional patches for SA and guidance will be required.)

Server Automation Alert Page 4

#### ©Copyright 2014 Hewlett-Packard Development Company, L.P.

Hewlett-Packard Company shall not be liable for technical or editorial errors or omissions contained herein. The information provided is provided "as is" without warranty of any kind. To the extent permitted by law, neither HP or its affiliates, subcontractors or suppliers will be liable for incidental, special or consequential damages including downtime cost; lost profits; damages relating to the procurement of substitute products or services; or damages for loss of data, or software restoration. The information in this document is subject to change without notice. Hewlett-Packard Company and the names of Hewlett-Packard products referenced herein are trademarks of Hewlett-Packard Company in the United States and other countries. Other product and company names mentioned herein may be trademarks of their respective owners.

Server Automation Alert Page 5