

HP OSI Transport Services/9000 Release Notes

Edition 1



32070-90049

HP 9000 Networking

E1100

Printed in: U.S.A.

© Copyright 1997, Hewlett-Packard Company.

Legal Notices

The information in this document is subject to change without notice.

Hewlett-Packard makes no warranty of any kind with regard to this manual, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Warranty. A copy of the specific warranty terms applicable to your Hewlett-Packard product and replacement parts can be obtained from your local Sales and Service Office.

Restricted Rights Legend. Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD COMPANY 3000 Hanover Street Palo Alto, California 94304 U.S.A.

Use of this manual and flexible disk(s) or tape cartridge(s) supplied for this pack is restricted to this product only. Additional copies of the programs may be made for security and back-up purposes only. Resale of the programs in their present form or with alterations, is expressly prohibited.

Copyright Notices. ©copyright 1983-97 Hewlett-Packard Company, all rights reserved.

Reproduction, adaptation, or translation of this document without prior written permission is prohibited, except as allowed under the copyright laws.

©copyright 1979, 1980, 1983, 1985-93 Regents of the University of California

This software is based in part on the Fourth Berkeley Software Distribution under license from the Regents of the University of California.

©copyright 1980, 1984, 1986 Novell, Inc.

©copyright 1986-1992 Sun Microsystems, Inc.

©copyright 1985-86, 1988 Massachusetts Institute of Technology.

©copyright 1989-93 The Open Software Foundation, Inc.

©copyright 1986 Digital Equipment Corporation.

©copyright 1990 Motorola, Inc.

©copyright 1990, 1991, 1992 Cornell University

©copyright 1989-1991 The University of Maryland

©copyright 1988 Carnegie Mellon University

Trademark Notices. UNIX is a registered trademark in the United States and other countries, licensed exclusively through X/Open Company Limited.

X Window System is a trademark of the Massachusetts Institute of Technology.

MS-DOS and Microsoft are U.S. registered trademarks of Microsoft Corporation.

OSF/Motif is a trademark of the Open Software Foundation, Inc. in the U.S. and other countries.

Contents

1. HP OSI Transport Services/9000 Release Notes

Who should read this Release Notes	10
Announcements	11
What's new In this Version?	12
Features	12
Benefits	12
OTS support for OnLine Replacement of LAN and X.25 cards.	14
Known Problems and Workarounds	16
Compatibility and Installation Requirements	18
Software Requirements	18
Hardware Requirements	18
Disk Space Requirements	18
Installation Instructions	18
Patches and Fixes in this Version.	19

Contents

Printing History

The manual printing date and part number indicate its current edition. The printing date will change when a new edition is printed. Minor changes may be made at reprint without changing the printing date. The manual part number will change when extensive changes are made.

Manual updates may be issued between editions to correct errors or document product changes. To ensure that you receive the updated or new editions, you should subscribe to the appropriate product support service. See your HP sales representative for details.

First Edition: November 1997 (HP-UX Release 11.0)

1 **HP OSI Transport Services/9000
Release Notes**

Who should read this Release Notes

This edition of the HP OSI Transport Services/9000 Release Notes contains the current release notes for version C.11.00 for HP-UX 11.11.

If you are considering updating to OTS/9000 version C.11.00 from OTS/9000 version C.08.00, read the release notes for version C.09.02 also.

If you are considering updating to OTS/9000 version C.11.00 from OTS/9000 version C.07.00 for HP-UX 10.20, or earlier, you may want to read the release notes for version C.08.00 and the release notes for version C.09.02 also.

NOTE

NOTE: The following release notes is also available online when the OTS/9000 product is installed. Please see `/opt/ots/doc/README_C1100` for an ASCII version of the release notes.

Announcements

HP OSI Transport Services/9000 (OTS/9000) is the OSI networking stack of HP-UX. It provides functions of OSI Layers 3 (Network), 4 (Transport), 5 (Session), 6 (Presentation) and ACSE/ROSE over X.25, FDDI and IEEE802.3 LAN interfaces. It also provides RFC1006 that allows users to run OSI Services over TCP connections. Applications can use OTS/9000 via Application Program Interfaces (APIs) to layers 4, 5, 6 and ACSE/ROSE application entities.

What's new In this Version?

HP OSI Transport Services/9000 version C.11.00 contains several new features and functionalities.

Features

HP OTS/9000 version C.11.00 provides the following features:

•Dynamic restart

OTS stack can now be stopped and started again, thus allowing the modifications of all the OTS configuration parameters.

Use the command 'otsstop' to stop the OTS stack. Once OTS is stopped, all the communication end points (CEPs) being used by OTS applications will no longer be usable. OTS will try to do a graceful disconnect on all the active connections. Once OTS stop is complete, the OTS stack can be restarted by using the command 'otsstart'. Any change in the OTS configuration files will take effect.

•Support for On Line Replacement(OLR) of LAN and X.25 cards.

With HP-UX 11.11 online replacement of LAN and X.25 cards is supported on N-Class, L-Class and SD-Class systems. OTS has been enhanced to work with on line replacement of LAN and X.25 cards.

For more information on OLR, refer HP-UX 11.11 Release Notes.

Benefits

Upgrading to HP OTS/9000 version C.11.00 will provide the following benefits:

• Dynamic Restart

OTS stack can now be stopped and restarted without a system reboot. This would enable :-

- changing NON-DYNAMIC configuration parameters in ots_parms (such as clns_net_entity_title, clns_route_cache_size, clns_dynamic_nsaps, etc.) and subnet configuration parameters for any configured subnet in ots_subnets, which earlier needed a reboot.
- Adding new subnets in ots_subnets.

- Deleting existing subnets from the configuration in `ots_subnets`.
- Support for On Line Replacement(OLR) of LAN and X.25 cards.
- Support for HP-UX version 11.11. If you wish to upgrade to HP-UX version 11.11, you must also upgrade to HP OTS/9000 version C.11.00.
- Updated documentation set with HP OTS/9000 version C.11.00.

OTS support for OnLine Replacement of LAN and X.25 cards

•On Line Replacement of LAN cards

When LAN cards configured in OTS are replaced, OTS applications using those interfaces will not be able to communicate further till the replaced interfaces have been activated. All outbound OSI packets over those interfaces will be dropped. The applications will be able to resume communication once the interfaces become active.

There is a possibility that the applications may exit with an error due to the transport layer aborting the connection when it fails to send the packets after repeated retransmissions. In such cases, the applications will have to be restarted. If the interface is activated before the transport layer encounters the retransmission limit, the applications will continue without problems.

•On Line Replacement of X.25 cards

When X.25 cards configured in OTS are replaced, OTS applications using that interface will be aborted with an error. The applications will have to be restarted once the replaced interface has been activated.

For more information on OLR, refer to the product specific documentation and HPUX 11.11 Release Notes.

- Note that OTS support for OLR applies for those interfaces that are already configured for use by OTS in `ots_subnets`.
 - This does not require OTS to be stopped.
 - This means that replacing a LAN card would affect only those applications using that subnet. This would not affect applications running on other configured subnets such as RFC1006, X.25 (CONS/CLNS) or even other CLNS LAN subnets. Only those applications running on the subnet for which the particular interface has been configured would be affected. Again, in case of LAN, as mentioned above, the impact would depend on whether the transport layer aborts the connection due to the retransmission limit being reached.

For example, if there are two CLNS LAN subnets (say `snet1` and `snet2`), using LAN interfaces `lan1` and `lan2`, if `lan1` were to be replaced, this would affect only applications running on `snet1`. Applications running over `snet2` would not be affected.

- In case of X.25, if the interface being replaced is a multi-port card, and if more than one port of this card is configured for use in `ots_subnets`, then replacing this card would affect all applications using any such subnets.
For example, if there are two CONS/X.25 subnets (say `snet1` and `snet2`) and 1 CLNS/X.25 subnet (say `snet3`) configured in OTS to use ports 1, 2 and 3 respectively of a 4-port X.25 card, replacing this X.25 card would affect all applications running over `snet1`, `snet2` and `snet3`.

Known Problems and Workarounds

- When MC/ServiceGuard initiates a local LAN switchover for HP OTS/9000 from one LAN card to another and then switches back to the first LAN card within 120 seconds, some operations to the first LAN card may fail. This is because previous LAN card information is still in the ESH table. If this happens, wait until after 120 seconds from the first switchover and try the switchover again.
- In C.11.00 version of OTS, if a local LAN switchover occurs when OTS is running and OTS is then stopped, OTS configuration files would still contain a reference to the primary LAN interface. So a restart would cause OTS to come up with the primary LAN interface instead of the switched/secondary LAN interface.

The above problem may also happen if OTS is started subsequent to a local LAN switchover.

A workaround is to verify that the interface configured for use in OTS is currently the functional LAN interface, before restarting OTS.

- With RFC1006 subnet configured in `ots_subnets`, `osiconfchk` would report the following warning:

```
:::::::::::::
/etc/opt/ots/conf/ots_subnets
:::::::::::::
Line 28:
    ->snet_socket_size           4096
    Warning: Unknown keyword. Line will be ignored.
    (CHK011)
NOTE: This line cannot be corrected with osiconf.
    (CHK080)
```

```
Line 29:
    ->snet_tcp_nodelay           0
    Warning: Unknown keyword. Line will be ignored.
    (CHK011)
```


NOTE: This line cannot be corrected with osiconf.
(CHK080)

These warnings may safely be ignored, without any
serious consequences.

Compatibility and Installation Requirements

Software Requirements

- HP-UX 11.11 operating system
If you are currently running an older version of HP-UX, you must upgrade to HP-UX 11.11 before installing HP OSI Transport Services/9000 version C.11.00.
- HP 9000 networking link products such as HP LAN/9000, HP FDDI/9000 and HP X.25 products (High-Performance STREAMS-X25, ACC/X.25).

Hardware Requirements

- HP 9000 Servers
- Installation/Update hardware such as:
 - DDS tape drive
 - CDROM drive
 - Networking link adapter (e.g. HP LAN/9000 card)

Disk Space Requirements

- 85 MB of disk space

Installation Instructions

A reboot is required for installing HP OTS/9000. The reboot is required to rebuild the HP-UX kernel with HP OTS/9000.

The "Installing and Administering HP OTS/9000" manual (HP Part Number 32070-90030) contains complete instructions for installing this product. See that document for detailed instructions.

Patches and Fixes in this Version

HP OTS/9000 version C.11.00 incorporates several fixes as available via patch PHNE_17859 to be applied to OTS/9000 versions C.09.00, C.09.01, or C.09.02.

The following section describes the new fixes available in PHNE_17859 and the additional fix in this version:

1. CR JAGaa32750

Symptom Description

otslogd should report an informative message when OTS drivers are missing in system configuration. In such a case, the following message is logged in `/var/opt/ots/OTS.startlog` when OTS is started:

```
ERROR: Can't open streams  
device: Network is down.
```

Defect Description

If OTS/9000 is installed on a system without X.25 or LAN product installed, the corresponding OTS drivers are not configured in the system configuration file. Hence OTS fails to start up, logging a message in the file `/var/opt/ots/OTS.startlog`.

Resolution

Code has been modified to report the actual cause of the problem. Also, the message displayed on the screen during OTS startup has also been modified to point the user to the above mentioned log file for more information.

2. CR JAGab47033

Symptom Description

New occurrence of panic in `prctr42()`.

Defect Description

OTS panics in `prctr42()`, because OTS is unable to handle all the errors in CLNP re-assembly.

Patches and Fixes in this Version

Resolution	CLNP re-assembly function has been modified to handle all the error conditions.
3. CR JAGab65123	
Symptom	Panic in sx25_reactivate()/qenable()
Defect Description	When an X.25 connection channel is suspended due to temporary lack of resources, the references in the suspended queue were not removed when the resources became available later, if the queue had only one element.
Resolution	The code was modified to remove the queue entries properly.
4. CR JAGab68119	
Symptom	OTS cannot start with "-i" option because otsstart script loops indefinitely.
Defect Description	otsstart script loops indefinitely when used with -i option, because the option -i was not parsed correctly and the error returned from getopt(1m) was not correctly handled.
Resolution	otsstart script has been changed to parse -i option correctly
5. CR JAGab15222	
Symptom	OTS panic in Xosidump or OsiUnlinkBseg.
Defect Description	OTS panic in Xosidump or OsiUnlinkBseg. The reason is either a "DOM memory error" or "Magic number mismatch". In either case, it is due to accessing an invalid pointer. This happens when the dispatcher tries to reactivate a previously suspended channel, which ideally should have been removed from the suspended queue.

Resolution	The code has been modified to check for suspended channels whenever a destructive interaction arrives on a channel. If the channel on which the interaction arrives is present in the list of suspended channels, the channel is removed from the list so that we don't receive any more interactions on it.
6. CR JAGab47102	
Symptom	Customer needs to have TCP_KEEPALIVE option for RFC1006 OSI connections.
Defect Description	OTS/RFC1006 does not enable the TCP_KEEPALIVE option which enables TCP to detect physical layer down conditions. Hence the application is not informed of lower layer failures.
Resolution	The OTS/RFC1006 code has been modified to enable the option. A new option has been added to 'otsstart' which may be used to enable this functionality during OTS startup.
7. CR JAGaa43858	
Symptom	OTS panic in OsiSndInterUp()
Defect Description	The panic was due to a message being received by OSIAM when the context state is O_DIS. This happened due to the context cleanup not being complete when the context is in O_DIS state.
Resolution	The problem has been fixed by nsuring that the context cleanup is complete.
8. CR JAGab77869	
Symptom	Unable to add NSAP after deleting the last NSAP displayed by otsshowsaps.

Patches and Fixes in this Version

Defect Description	The problem was because of incorrect handling of NSAP removal. This happens when maximum number of dynamic NSAPs (limited by <code>clns_dynamic_nsaps</code> , <code>cons_dynamic_nsaps</code> or <code>rfc_dynamic_nsaps</code>) are added and the last dynamic NSAP is removed.
Resolution	The code for NSAP deletion has been modified to correct this problem.
9. CR JAGab83428	
Symptom	<code>osiconfchk</code> dumps core when <code>X25INIT_FILE</code> parameter exceeds 28 characters.
Defect Description	The problem was due to the small array used to store the file name. It used to overflow the array and cause a core dump.
Resolution	The code has been modified to ensure that the array is large enough to hold long file names.
10. CR JAGab76311	
Symptom	OSI stops communication. When OTS receives a broadcast or a multicast packet on a lan subnet, whose destination address is neither <code>all_es_address</code> nor <code>all_is_address</code> , OTS stops communication on that subnet. Following message is logged in the syslog file. vmunix: hp_lan_up:multicast: NO OPT
Defect Description	An invalid incoming PDU results in an error condition in the lower read service procedure of the OTS LAN module. Once this PDU is processed,

Resolution	the service procedure does not get scheduled, since the queue is not enabled. The lower read queue is enabled after processing of the erroneous PDU.
11. CR JAGab70710	
Symptom	64-bit APLI/XAP/ROSE libraries dump core in mutli-threaded environment.
Defect Description	64 bit APLI, ROSE and XAP libraries dump core in multi-threaded environment. This was because these libraries were not compiled with _PROTOTYPES preprocessor directive.
Resolution	OTS libraries are now compiled with _PROTOTYPES preprocessor directive.
12. CR JAGab78402	
Symptom	otsdelnsap not able to remove RFC1006 dynamic NSAPs.
Defect Description	otsdelnsap was unable to remove RFC1006 dynamic NSAPs when the number of statically configured X.25 CONS NSAPs was more than two. This is because OTS used to treat the dynamic RFC1006 NSAPs as statically configured and not allow their deletion.
Resolution	Fix is to consider RFC1006 NSAPs separately and allow their deletion, irrespective of the number CONS X.25 subnets.
13. CR JAGaa93170	
Symptom	System crashing in OTS code showing OsiDmnIoctl() at the top of the stack trace.

Resolution

I_UNLINK is handled for the LAN LAM queue so that the OTS private data structures remove references to these lower unlinked queues so that no further messages are sent on these queues.

15. CR JAGac42758

Symptom

Potential memory corruption. This can lead to Data page fault panics.

Defect Description

Memory corruption while receiving a fragmented TSDU because of using an uninitialized variable. This is just a potential problem in 11.00.

Resolution

Using the correct variable instead of the uninitialized variable.

16. CR JAGab70711

Symptom

Makefiles for 64-bit APLI/ROSE/XAP threads demo programs not available.

Defect Description

There were no Makefiles for building 64-bit APLI/ROSE/XAP threads demo programs and some of the files were not 64-bit clean.

Resolution

The APLI/ROSE/XAP demo source files have been made 64 bit clean, and 64 bit Makefiles have been made available.

HP OSI Transport Services/9000 Release Notes
Patches and Fixes in this Version